


LEGEND

- ✦ TIMBER BOLLARDS
- ⊙ BENCH MARK
- ⊙ ELECTRIC L/POLE
- SEAT
- ⊞ TELECOM PIT
- ⊙ SEWER PIT
- ⊙ FIRE HYDRANT
- ⊞ SIDE ENTRY PIT
- ⊞ JUNCTION PIT
- ⊞ GRATED PIT
- ⊙ TREE
- TGP OF KERB
- FENCE LINE
- EDGE OF PLANTATION

NOTE:
CONTOURS SHOWN TO AHD
AT 0.25m INTERVAL, FROM
SURVEY COMPLETED DEC. 1996



D.C.E.
Dalton Consulting Engineers Pty Ltd
73 Antares Road, Raitwyn VIC 3103
Ph 03 9017 2560 Fax 031 9017 2000
ACN 253 226 177

WHITEHORSE
BLACKBURN CREEKLAND
EXISTING FEATURES
SURVEY PLAN

REF 56931-
DATE: 10/11/97
SCALE: 1:1000

Map 1d. Vegetation Quality and Condition Assessment: Main St. to Blackburn Rd.